

# Service Tips from the Pros




brought to you by our friends at Farm & City Insurance Services



## Schwintek Slide Mechanism Noise.

There is the possibility of a popping or squeaking noise from the Schwintek slide mechanism when the motor home is in transit. Lubrication with CRC product should eliminate the noise in most cases. (The 'gibbs' and 'coupler' can be seen if you gently pull the rubber seal back on the exterior, at the rails.)

Lubricate "gibbs" in the locations above and below gear rail roller. Also lubricate the motor "coupler" with CRC Industrial Power Lube with PTFE (use extension nozzle to direct lubrication).



### CRC Industrial Power Lube with "PTFE"

CRC part number  
(CRC03045) (purchase  
locally)

