

Service Tips from the Pros











HDMI Video Selection System


Certain 2012 and newer Winnebago Adventurer, Journey and Tour as well as Itasca Suncruiser, Meridian and Ellipse coaches are built with the HDMI Video Selection System. This system allows you to watch high definition video from multiple sources on multiple TV's at the same time. You can select either Home Theater, Satellite Receiver 1, Satellite Receiver 2, or auxiliary. TV's connected to this system are the Lounge TV, 2nd Lounge TV (if equipped), Bedroom TV, and Exterior Entertainment Center TV. Winnebago Industries, Inc. has used 2 generations of this system since its introduction in 2012.

Our supplier, Pace International, has provided the following 'HDMI Matrix Generation Comparison Sheet' for reference in obtaining repair parts for either system. For proper operation it is important that a failed component be replaced with one of the same generation. For example, you should not replace a Generation 1 Balun with a Generation 2 part. The following comparison sheet should be used as a reference to help verify that any replacement parts are for the same generation system.

You may also access several related YouTube videos at <http://www.youtube.com/playlist?list=PL28AB7E84CD14FD7E>

HDMI MATRIX GENERATION COMPARISON

GENERATION 1	GENERATION 2
<p>#180504-01-000 Old HDMI 4x4 Matrix</p> 	<p>#180504-06-000 New HDMI 4x4 Matrix</p> 
<p>#180504-02-000 Old Balun</p> 	<p>#180504-07-000 New Balun</p> 
<p>#180504-03-000 Old Infrared Receiver</p> 	<p>#180504-08-000 #180504-09-000 New Infrared Receiver</p> 
<p>#180504-04-000 Old Infrared Emitter</p> 	<p>#180504-10-000 New Infrared Emitter</p> 
<ul style="list-style-type: none"> Glossy black color Now says BluRay New labeling 	<ul style="list-style-type: none"> Glossy black color Light-up numbers Reset button Only one IR Receiver
<ul style="list-style-type: none"> Now with In-wall Infrared Receiver Two conductor plug-in 	<ul style="list-style-type: none"> Smaller in size Sticks right to source



Pace International
 3582 Technology Drive 1.800.444.PACE (7223)
 Rochester, MN 55901 www.paceintl.com